

REPAIR FACILITY	REPAIR CATEGORIES
911 Safety Equipment LLC 329 E. Main Street Norristown, PA 19401	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier
Advanced Fire Gear Repair 1902 Campus Place, Suite 2 & 3 Louisville, KY 40299	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier
AFECO dba SoCal P.P.E. 2717 Boston Ave. San Diego, CA 92113	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Alameda County Fire Department 2194 Williams St. San Leandro, CA 94577	Advanced Cleaning & Advanced Inspection PCA Advance Outer Shell Defender M Camo Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier
Arizona PPE Recon, Inc. 520 S. 52nd St., Suite 202 Tempe, AZ 85281	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair Gold Moisture Barrier
Associated Fire Safety Maintenance #106 – 3070 Norland Ave Burnaby BC V5B 3A6	Outer Shell Thermal Liner WL Gore Crosstech 2 Layer Type 2C Moisture Barrier WL Gore Black Crosstech Type 2F Moisture Barrier WL Gore RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier Stedfast Stedair Gold Moisture Barrier
Choice Clean Gear LLC 369 Turner Industrial Way Aston, PA 19014	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore RT7100 Type 3D Moisture Barrier Stedfast Stedair 4000 Moisture Barrier

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at [ann.overbaugh@intertek.com](mailto:ann.overbaugh@intertek.com)

REPAIR FACILITY	REPAIR CATEGORIES
City of Kirkland (Organization) 123 5th Ave. Kirkland, WA 98033	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Type 2F Moisture Barrier
Clean Heroes 10 Rockwell Drive Stewiacke, NS B0N2J0	Advanced Cleaning & Advanced Inspection <b>Not Verified for Repair</b>
D & D Mountain Air Cleaners 309 South Paseo De Onate Espanola, NM 87532	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier
Deering Cleaners 602 N. Capitol Ave. Indianapolis, IN 46240	Advanced Cleaning & Advanced Inspection <b>Not Verified for Repair</b>
Delta Industrial Services and Supply 3159 Summit Dr. Port Neches, TX 77651	Advanced Cleaning & Advanced Inspection <b>Not Verified for Repair</b>
1.50 Cleaners PPE Division 1005 W. Nolana Suite C McAllen, TX 78504	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier
Done Right Fire Gear Repair 7621 Maryland Ave. Hudson, Florida 34667	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at [ann.overbaugh@intertek.com](mailto:ann.overbaugh@intertek.com)

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
<p>Don's Leather Cleaning. Inc. 3713 East Lake Street Minneapolis, MN 55406</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell</p>
<p>ECMS, Inc. 16821 Knott Ave. La Mirada, CA 92638</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>ECMS, Inc. 4200 West Russell Road, Suite 113 Las Vegas, NV 89118</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier W.L. Gore Parallon Type B2 Liner System Stedfast Stedair 3000 Moisture Barrier</p>
<p>ECMS, Inc. 1809 Perlata Street Oakland, CA 94607</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier</p>
<p>ECMS, Inc. 4647 South 33rd Street Phoenix, AZ 85040</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stediar Gold Moisture Barrier</p>

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at [ann.overbaugh@intertek.com](mailto:ann.overbaugh@intertek.com)

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
<p>ECMS, Inc. 1185 South 300 West Salt Lake City, UT 84101</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>
<p>ECMS, Inc. 6507 S. 208th St. Kent, WA 98032</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>
<p>Fire Safety Services Inc 6228 Road 95 Huntsville, OH 43324</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>Fire W.I.R.E. LLC 813 EL Serrano CT SW Albuquerque, NM 87105</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>
<p>Fort Worth Fire Department (Organization) 2900 W. Bolt St. Fort Worth, TX 76110</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell - PBI Matrix (Gemini) Thermal Liner - Quantum 3D W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>Georgian Firegear Service 103 Bayfield Street Barrie Ontario Canada QC L4M 3A9</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier</p>

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at [ann.overbaugh@intertek.com](mailto:ann.overbaugh@intertek.com)

REPAIR FACILITY	REPAIR CATEGORIES
<p>Isotech Instrumentation, Inc. 2250, Andre C. Hamel Drummondville QC J2C 8B1</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>Maryland Fire Equipment 12284 Wilkins Avenue Rockville, MD 20852</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair Gold Moisture Barrier</p>
<p>Minerva Bunker Gear Cleaners of Ohio Corp. 4949 Northcutt Place Dayton, OH 45414</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier Stedfast Stedair Gold</p>
<p>Minerva Bunker Gear Cleaners of Ohio Corp. 4949 Northcutt Place Dayton, OH 45414</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier Stedfast Stedair Gold</p>
<p>Minerva Bunker Gear Cleaners 780 East 134th Street Bronx, NY 10454</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at [ann.overbaugh@intertek.com](mailto:ann.overbaugh@intertek.com)

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
Minerva Bunker Gear Cleaners Corp. EIN#45-4661121 3839 Corporation Circle Charlotte, NC 28216	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
MBGC LLC d/b/a Minerva Bunker Gear Cleaner 3795 NW 38 St. Miami, FL 33142	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore RT7100 Type 3D Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Minerva Bunker Gear Cleaners Corp. 3301 South Field St. Lakewood, CO 80227	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
National Tailors 2123 Strawberry Rd Pasadena, TX 77502	Advanced Cleaning & Advanced Inspection Outer Shell
Native Hawaiian Veterans dba American Safety 3375 Koapaka Street, F-238-20 Honolulu, HI 96819	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 4000 Moisture Barrier
Northern Safety and Industrial 3750 North I-44 Service Road Oklahoma City, OK 73112	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier Stedfast Stedair Gold Moisture Barrier
Rainbow Cleaners 44 Queen Anne Road Bogota, NJ 07603	Advanced Cleaning & Advanced Inspection Outer Shell Thermal Liner

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at [ann.overbaugh@intertek.com](mailto:ann.overbaugh@intertek.com)

REPAIR FACILITY	REPAIR CATEGORIES
<p>Roundhouse Bunker Gear Repair Services LLC 1800 Yankee Hill Rd Lincoln, NE 68512</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier</p>
<p>Scott's PPE Recon 827 Black Diamond Way, Buliding C Lodi, CA 95240</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair Gold Moisture Barrier</p>
<p>Shamrock Gear Restoration LLC 5824 Akron Cleveland Road Hudson, OH 44236</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Black Crosstech Type 2F Moisture Barrier Stedfast Stedair 3000 Moisture Barrier</p>
<p>Solutions of New Orleans 4929 E. Judge Perez Drive</p>	<p>Advanced Cleaning &amp; Advanced Inspection Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier</p>
<p>The Fire Industry Repair &amp; Maintenance Building C #5 624 Beaverdam Road NE Calgary AB Canada T2K 4W6</p>	<p>Advanced Cleaning &amp; Advanced Inspection Stedfast Stedair Gold Moisture Barrier Outer Shell Thermal Liner W.L. Gore Crosstech 2 Layer Type 2C Moisture Barrier W.L. Gore Black Crosstech Type 2F Moisture Barrier W.L. Gore Crosstech RT7100 Type 3D Moisture Barrier Stedfast Stedair 3000 Moisture Barrier Stedfast Stedair 4000 Moisture Barrier Stedfast Stedair Gold Moisture Barrier</p>

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at [ann.overbaugh@intertek.com](mailto:ann.overbaugh@intertek.com)



Total Quality. Assured.

# ETL NFPA 1851-2014 VERIFIED ISP's AND ORGANIZATIONS

REPAIR FACILITY	REPAIR CATEGORIES
<p>This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at <a href="mailto:ann.overbaugh@intertek.com">ann.overbaugh@intertek.com</a></p>	



Total Quality. Assured.