

ISP OR ORGANIZATION	VERIFIED SERVICES
<p>911 Safety Equipment LLC 9 S Forrest Ave. Norristown, PA 19401</p> <p>Valid Through: 02/13/2022</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast 488-200 Repair Tape
<p>Broadway Minerva Cleaners LLC dba Minerva Bunker Gear Cleaners 780 East 134 Street Bronx, NY 10454</p> <p>Valid Through: 06/30/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Delta Fire & Safety Inc. dba Delta Industrial Service & Supply 3159 Summit Drive Port Neches, TX 77651</p> <p>Valid Through: 10/31/2022</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>ECMS, INC. 517 W. Sunset Road Henderson, NV 89011</p> <p>Valid Through: 01/30/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •W.L. Gore Parallon Type B2 Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>ECMS, INC. 1635 Gramercy Road Salt Lake City, UT 84104</p> <p>Valid Through: 02/16/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape
<p>ECMS, INC. 1809 Peralta Street Oakland, CA 94607</p> <p>Valid Through: 02/16/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape
<p>ECMS, INC. 16821 Knott Ave. La Mirada, CA 90638</p> <p>Valid Through: 02/27/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>ECMS, INC. 6507 S. 208th Street Kent, WA 98032</p> <p>Valid Through: 03/09/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at ann.overbaugh@intertek.com

ISP OR ORGANIZATION	VERIFIED SERVICES
<p>ECMS, INC. 4647 S. 33rd Street Phoenix, AZ 85042</p> <p>Valid Through: 03/25/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Fire Safety Services, Inc. 6228 Road 95 Huntsville, OH 43324</p> <p>Valid Through: 09/24/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Fire W.I.R.E. LLC 3415 Bryn ^cawr Dr. NE Albuquerque, NM 87107</p> <p>Valid Through: 07/28/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Florida PPE Services, Inc. 970 Sunshine Lane, Units J/K Altamonte Springs, FL 32714</p> <p>Valid Through: 06/16/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Hawaiian Veterans dba Hawaii PPE 94-155 Leo'ole St., Suite D406 Waipahu, HI 96797</p> <p>Valid Through: 12/30/2022</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>HC Risk Reduction (Redline) 51 Lacombe St., Unit 4 Marlborough, MA 01752</p> <p>Mobile Unit Verified Cleaner Valid Through: 02/27/2023</p>	<p>Advanced Cleaning & Sanitization</p>
<p>Maryland Fire Equipment Corp. 12284 Wilkins Ave. Rockville, MD 20852</p> <p>Valid Through: 7/30/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape
<p>Minerva Bunker Gear Cleaners of Colorado Corp. 3301 S. Field Street Lakewood, CO 80227</p> <p>Valid Through: 6/30/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape

ISP OR ORGANIZATION	VERIFIED SERVICES
<p>Minerva Bunker Gear Cleaners of Ohio Corp. 620 Shiloh Springs Road Dayton, OH 45415</p> <p>Valid Through: 6/23/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Scott's PPE Recon 827 Black Diamond Way, Bldg. C Lodi, CA 95240</p> <p>Valid Through: 2/21/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>SoCal PPE, LLC 2146 Main Street San Diego, CA 92113</p> <p>Valid Through: 10/7/2022</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Solutions of New Orleans LLC 4929 E Judge Perez Dr. Violet, LA 70092</p> <p>Valid Through: 5/25/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Turnout Express LLC 1250 Scottsville Road, Suite 90 Rochester, NY 14624</p> <p>Valid Through: 11/30/2022</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Turnouts, LLC 5824 Akron Cleveland Road, Suite C Hudson, OH 44236</p> <p>Valid Through: 02/05/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>Turnouts, LLC 5225 North State Route 60 NW McConnelsville, OH 43756</p> <p>Valid Through: 02/05/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none"> •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
<p>This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at ann.overbaugh@intertek.com</p>	



Total Quality. Assured.

ETL NFPA 1851-2020 VERIFIED ISP's AND ORGANIZATIONS

ISP OR ORGANIZATION	VERIFIED SERVICES
<p>United Safety Group 4110 Butler Pike, Suite A-103 Plymouth Meeting, PA 19462 Valid Through: 05/27/2023</p>	<p>Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of:</p> <ul style="list-style-type: none">•Outer Shell•Thermal Liner•W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape•W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape•Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at ann.overbaugh@intertek.com