Intertek 545 E Algonquin Road, Suite H Arlington Heights, IL 60005 USA

Telephone: 847-439-5667 intertek.com

Public Notice: 17-30

## **PUBLIC NOTICE**

## Intertek Warns of Unauthorized ETL Certification Mark on LifeSpan Fitness DT-7 Treadmill Desks

Published: September 20, 2017

The following is a notification from Intertek that the LifeSpan Fitness Treadmill Desks identified below bear unauthorized Intertek Certification Marks for the United States and Canada. The products are not certified by Intertek and it is not known if they comply with relevant safety requirements.

Product	Treadmills with manually adjusted work surfaces Model DT-7
Description	
Manufacturer	LifeSpan Fitness
Number of Units	36 units with Serial Numbers associated with this labelling issue are as follows:  Serial Numbers:  BG13A00001-BG13A00167  BG13A00168-BG13A00334  BG13A00335-BG13A00521  BG13A00522-BG13A00708  BG13A00709-BG13A00888  BA13B00001-BA13B00160  BA13B00161-BA13B00223  BA13B00224-BA13B00410  BA14B00001-BA14B00187  BA14B00188-BA14B00374  BA14B00562-BA14B00561  BA14B00562-BA14B00748  BA14B00749-BA14B00935  BA14B01123-BA14B01122  BA14B01310-BA14B01496  BA14B01310-BA14B01496  BA14B01497-BA14B01683  BA14B01684-BA14B01870  BA15B00001-BA15B00187  BA15B00018-BA15B00374  BA15B00018-BA15B00374  BA15C00001~BA15C00187



	BA15C00188-BA15C00374
	BA15C00390-BA15C00489
	BA15C00490-BA15C00613
	BN13A00001-BN13A00003
	BN13A00004-BN13A00027
	BN13A00028-BN13A00067
	BN13A00088-BN13A00117
	BN13B00001-BN13B00032
	BN14A00001-BN14A00032
	BN14A00033-BN14A00076
	BA15C00375-BA15C00389
	BN15B00047-BN15B00063
	BN14A00033-BN14A00076
	BN15B00001-BN15B00046
	BN15A00001-BN15A00027
Identification	On Product: The product bears an unauthorized ETL Mark as follows:
	The cETLus Cetification Mark is missing the control number
Reported Hazards	Unknown
Sold at	Known to be sold at <a href="http://www.lifespan.com">http://www.lifespan.com</a> and may have been sold by
	other retailers.
What to do	Products should not be used and returned to the point of purchase.
	Distributors and retailer should discontinue sales and return all inventories
	to their supplier.

## **Nameplate Photographs**

