

545 E Algonquin Road, Suite H Arlington Heights, IL 60005 USA

Telephone: 847-439-5667 intertek.com

Public Notice ID: 2023-62 Page 1 of 2

Published: Revised: 8-Nov-23

Misrepresentation of Intertek Certified Product Labels

120 minute EIB - Stiffened Insulation Steel Fire Door

Notification Type:	Misuse of Certification Mark
Certification Type:	Not Intertek Certified
Notification	
intertek notifies public that we	e have been notified by the applicant that the labels identified below have been misrepresented as Intertek Certified.
Company Identification	
Steel Fire Egypt	
Product Identification	
For misrepresentation of certified	d product labels. Photos on Page 2
Client name: Steel Fire Eqypt	
Product : 120 minute EIB - Stiffen	ned Insulation Steel Fire Door
W/N Number: 21197	
,	
Hazard Involved	
Not Intertek Certified	
What To Do	scontinued and return to the point of purchase and the labels should be removed and returned to Intertek.



Published: Revised:

November 8, 2023

Photos and Images



545 E Algonquin Road, Suite H Arlington Heights, IL 60005 USA

Telephone: 847-439-5667 intertek.com

Public Notice ID: 2023-62 Page 2 of 2