

545 E Algonquin Road, Suite H Arlington Heights, IL 60005 USA

Telephone: 847-439-5667

intertek.com

Public Notice ID: 2024-08

Page 1 of 2

## **Misrepresentation of Intertek Certified Product Labels**

# Fire Doors 20" Door without Hose Stream (OS)

Notification Type:	Misuse of Certification Mark
Certification Type:	Not Intertek Certified

#### **Notification**

Published:

Revised:

Intertek notifies public that we have been notified by the applicant that the labels identified below have been misrepresented as Intertek Certified.

13-Feb-24

#### **Company Identification**

Builders FirstSource Inc (Layton, UT)

#### **Product Identification**

For misrepresentation of certified product labels. Photos on Page 2

Product: Fire Doors

Client Name: Builders FirstSource Inc (Layton, UT) Address: 1617 West Hill Field Road, Layton, UT 84041 PO# for label order that was lost: 6109876-00

W/N 00202 - qty 200 (SN 1394501-1394700) Label Description: 20" Door without Hose Stream (OS)

#### Hazard Involved

Not Intertek Certified

#### What To Do


Use should be immediately discontinued and return to the point of purchase and the labels should be removed and returned to Intertek.



Published: Revised:

February 13, 2024

### **Photos and Images**



Telephone: 847-439-5667

intertek.com

Public Notice ID: 2024-08

Page 2 of 2

